
Meridian 1

Remote Peripheral Equipment

Maintenance procedures

Document Number: 553-2601-500

Document Release: Standard 3.0

Date: December 1994

© 1990, 1994

All rights reserved

Printed in the United States of America

Information is subject to change without notice. Northern Telecom reserves the right to make changes in design or components as progress in engineering and manufacturing may warrant. This equipment has been tested and found to comply with the limits for a Class A digital device pursuant to Part 15 of the FCC rules.

SL-1 and Meridian 1 are trademarks of Northern Telecom.

Revision history

August 10, 1990

Standard, release 1.0. Reissued for compliance with Northern Telecom standard 164.0.

December 1, 1991

Standard, release 2.0. This document was reissued to include technical content updates. Due to the extent of changes, revision bars are not used.

December 1994

Standard, release 3.0. Reissued to include format changes, editorial changes and indexing. Due to the extent of the changes, revision bars are not used.

Contents

About this document	1
Equipment description	3
Fault detection	5
Overlay programs	5
Alarm indications	6
Fault clearing	7
Precautions	7
Option switches	7
Power	14
Faceplate layout	14
Disabling loop for testing	14
Carrier fault clearing	17
Radio carrier system	17
Land-line carrier systems	17
Looping options	20
Common causes of faults	20
Error measurement	22

List of figures

Figure 1	
RPE block diagram	4
Figure 2	
RPE fault-clearing procedures	8
Figure 3	
Carrier shelf circuit card faceplates	15
Figure 4	
Carrier looping options	18
Figure 5	
QPC99 maintenance jacks and looping switches	19

List of tables

Table 1	
Circuit card LEDs	16